

**PRODUCT:**

- ST9 Part # 140-0004: Journal Bearing

**MFR:** ST9 Gas & Oil LLC

**MODIFICATION:**

1) Three grooves added to the rod and cap half of the crankshaft journal bearing.

**DETAILS:** To facilitate more even lubrication across the crank journal, three oil grooves were added to the rod and cap halves of the journal bearings. Both sides have the same part number.


The bearings are installed together in the knuckle for QC then broken apart and installed on the crankshaft.



**Pic 1**  
**Journal Bearing With Grooves**



**Pic 2**  
**Journal Bearings in Knuckle**



**Pic 3**  
**Broken Apart Before Crankshaft Assy**

**FOR MORE INFORMATION CONTACT:**



Alex Booth

Product Manager

M: +1 (832) 326-6774

E: [booth.alex@ST9go.com](mailto:booth.alex@ST9go.com)

[www.ST9go.com](http://www.ST9go.com)